

South Central Area - TAG Meeting Minutes for Noting

01/04/2021 11 Items Page 1 of 2

(Area Committee Date: 21/04/2021)

	- Dublin City C				(Area Committee D	ato. 21/04/2021)			rage rorz
Iten	n Enquiry SP Ref	Topic	Road	Post	Request Description	Tag Result	Tag Comments	Request By	Received Se
1	7008491	Traffic Calming	NEWMARKET STREET (SC)	Dublin 8	"Children-at-play" signage and speed ramps.	Not Recommended	This area is within the new speed limits set by Dublin City Council for residential areas in parts of the city. As part of the new limits, "Speed limit" signs are erected at all points where there is a change of speed limit. Incorporated into these new signs there is a "Home Zone" and "Slow Zone" sign along with the speed limit. This is to warn motorists that it's a residential area and to expect children. It is felt that this sign would be sufficient to warn motorists. Additionally the request for speed ramps on Newmarket Street does not meet the criteria for a number of reasons. Dublin City Council does not install ramps on a 30km road and the straight part of the road is narrow and less than 200m.	the Public	15/04/2019 0
2	7015093	Children Crossing Sign	DONARD ROAD (SC)	Dublin 12	2 on the road.	Recommended	SR Recommended – Following an investigation the Area Engineer would recommend a W142 "Children At Play" sign at the entrance to Donard Road on the western side of the carriageway. This sign should be accompanied with road markings saying "Slow" ouside house number 87. Installed as of 09/03/2021.	TD	27/05/2020 0
3	7016944	Parking Restrictions	SOUTH CIRCULAR ROAD (SC)	Dublin 8	Convex mirror, or other measures, to eliminate traffic visibility issues at exit to Saint James's Wood.	Not Recommended	SR NOT RECOMMENDED – It would not be recommended to install a traffic mirror across from the entrance of Saint James's Wood apartment complex. The traffic department does not provide convex traffic mirrors as requested as they give a distorted view of approaching traffic which is potentially hazardous and also because such mirrors would attract a high degree of vandalism with associated maintenance costs Furthermore, after a site visit the area engineer did not encounter any issues exiting on to the South Circular Road. They noted that there is a yellow box at this particular entrance, there are two double yellow lines on either side of the entrance measuring 8.5m and 6.1m. This greatly improves visibility at the entrance and allows the drivers to exit in a safe manner. With this in mind no additional measures are recommended.	5	17/09/2020 2
4	7017308	Disab Park Bay Residential	CLARENCE MANGAN ROAD (SC)	Dublin 8	outside 31.	Recommended	SR recommended – After a site visit it was noted that there was a high demand for parking in the area. For this reason I would recommend a disabled parking bay outside number 31 Clarence Mangan Road in the proximity of LS2 (not outside 31 Oscar Square which is beside it and is where google maps brings you). Stat – install a disabled bay parallel to the kerb centred outside number 31 Clarence Mangan Road. in the proximity of LS2.	Member of the Public	12/10/2020 0
5	7018166 Q3 SCAC 12/20	Double Yellow Lines	JAMES'S WALK (SC)	Dublin 8	on the road	Recommended	SR recommended Stat 1 -The area engineer has recommended that DYL be installed on the south side of Glenmalure Villas/ James's Walk. Starting 7.5m east of LS3 stretching for approx. 22m in an easterly direction to meet with cycle stands.	Councillor	30/11/2020 0



South Central Area - TAG Meeting Minutes for Noting

01/04/2021 11 Items Page 2 of 2

(Area Committee Date: 21/04/2021)

Iten	n Enquiry	SP Ref	Topic	Road	Post	Request Description	Tag Result	Tag Comments	Request By	Received Sec
6	7018476	Q 32 12/2020	TAG General Engineer Query	DRUMFINN AVENUE (SC)	Dublin 10	D Request for Children At Play signs	Recommended	SR Recommended – Following an investigation the Area Engineer would recommend a W142 "Children At Play" sign on the approach to the park on Drumfinn Ave on the southern side of the carriageway across from LS9 near house number 47 Drumfinn Ave. A second should also be installed on Cleggan Park on the approach to the park. This should be installed on the western side of the road and in the vicinity of 51 Cleggan Park. These signs should be accompanied with road markings saying "Slow".	Councillor	22/12/2020 0
7	7018561		3.5 Tonne Limit	WALKINSTOWN PARADE (SC)	Dublin 12	2 on the road.	Recommended	SR Recommended - Following investigation a 3.5 tonne ban is recommended for Walkinstown Parade. The signs will need to be located at all 3 entrances. The first will need to be at the entrance to Walkinstown Parade from the Long Mile Road in the vicinity of LS12. The second will need to be located at the junction of Walkinstown Parade and Kilnamanagh Road in the vicinity of LS16. The third will need to be located at the junction of Walkinstown Parade and Walkinstown Drive in the vicinity of LS1.	the Public	11/01/2021 0
8	7018747		P&D/Permit Parking	RIALTO COTTAGES (SC)	Dublin 8	Parking scheme for Rialto Cottages, Rialto Street, Rialto Park & Rialto Court.	Recommended	Accepted at ballot of residents, Hours Mon-Sat 07.00-24.00. 142 votes returned, 90 for, 28 against, 24 spoilt votes. The pro-rata vote was 77 for and 27 against.	Member of the Public	22/01/2021 1
9	7018937	Q 26 02/2021	Traffic Calming	LOUGH CONN ROAD (SC)	Dublin 10	O on the road	Not Recommended	SR not recommended. The Area Engineer carried out a speed survey in 2017 on this road at two separate locations. The results of the speed survey came back with very low readings for speed in the area with only a 4.8% and 1.71% speed violation during the 24hr period. The Area Engineer carried out another 24hr speed survey in October 2020 on Lough Conn Road. The results of the speed survey came back with even lower speed violations with a reading of 0.88% during the 24hr period and an 85th percentile reading of 35km/hr in a speed limit of 50km/hr. With this information it would not be recommended to have traffic calming measures installed.		05/02/2021 1
10	7019020		Disab Park Bay Residential	SOUTH CIRCULAR ROAD (SC)	Dublin 8	552 South Circular Road.	Recommended	SR recommended – After a site visit it was noted that there was a high demand for parking in the area . For this reason I would recommend a disabled parking bay in the vicinity of 552 South Circular Road. Stat – install a disabled bay parallel to the kerb starting 3m east of LS1 on Glenmalure Park on the northern side of the carriageway.	Member of the Public	12/02/2021 0
11	7019387		Double Yellow Lines	SPERRIN ROAD (SC)	Dublin 12	2 Double yellow lines to be added to prevent all day parking which prevents people turning in the cul de sac after dropping people off		SR Recommended – After a site visit the Area Engineer noticed all day parking at this turning circle at the end of the Cul-De-Sac on Sperrin Road. The Area Engineer would recommend Double Yellow Lines at this location	Internal	08/03/2021 0
								Stat – Starting at LS1 on the western side of Sperrin Road, install Double Yellow Lines in an northerly direction right and around the circle to end opposite LS1 on the eastern side of the carriageway(Excluding vehicle entrances).		