



South Central Area - TAG Meeting Minutes for Noting

(Area Committee Date: 17/10/2018)

Item	Enquiry	SP Ref	Topic	Road	Post	Request Description	Tag Result	Tag Comments	Request By	Received	Sec
1	7000473		School Keep Clear	ROSSMORE AVENUE (SC)	Dublin 10	outside 49, Training college	Not Recommended	It is not recommended to install parking restrictions, such as placing "School Keep Clear" across entrances, where restrictions are already covered under the law. Under The Road Traffic (Traffic & Parking) Regulations, Section 36 paragraph(2) g; "A vehicle shall not be parked in any place, position or manner that will result in the vehicle obstructing an entrance or an exit for vehicles to or from a premises, save with the consent of the occupier of such premises;" Infringements should be reported to Dublin Street Parking Services tel no. 01 6022500 or the Gardaí as they occur.	Member of the Public	20/11/2017	0
2	7002951		Double Yellow Lines	SLIEVEBLOOM ROAD (SC)	Dublin 12	outside entrance to apartment complex	Recommended	Double Yellow Lines on the west side of the roadway, starting from a point 5 metres south of Public Lamp Standard No. 3 extending northwards for 19 metres (including the entrance).	Internal	18/05/2018	0
3	7003127		Children Crossing Sign	INCHICORE PARADE (SC)	Dublin 8	throughout the CIE works estate	Not Recommended	It was not recommended to install a 'Children Crossing' sign on Inchicore Parade as these roads are traffic calmed already. Such signs would not be recommended in accordance with the City Council's criteria.	Member of the Public	30/05/2018	3
4	7003537		Children Crossing Sign	WINDMILL PARK (SC)	Dublin 12	on Windmill Park and Windmill Road .	Not Recommended	It is not recommended to install a 'Children Crossing' sign on Windmill Park or Windmill Road as these roads are traffic calmed already. Such signs would not be recommended in accordance with the City Council's criteria.	Minister	27/06/2018	0
5	7003721		Traffic Calming	CLARENCE MANGAN ROAD (SC)	Dublin 8		Not Recommended	Speed survey confirms that there is no speed issue on this road as the 85th percentile is 28km/h	Member of the Public	10/07/2018	0
6	7004395		Speed Ramps	LA TOUCHE DRIVE (SC)	Dublin 12	Speed ramps requested.	Not Recommended	After a site inspection the area engineer did not notice any speeding in the area at that time so he carried out a 24hr speed survey for La Touche Drive. The results of the speed survey came back with readings of 0.26% speed violation and after studying the 85 percentile reading its only 36km/h during the 24hr period. With this information it would not be recommended to have ramps installed	Member of the Public	20/08/2018	0
7	7004592		Speed Ramps	CHAMBER STREET (SC)	Dublin 8		Not Recommended	After a site inspection the area engineer would not recommend additional ramps on Chamber Street as the straight part of the road only measures approx 165m and has 3 ramps and on street parking which acts as a natural traffic calming technique on it already. The area engineer believes that another speed ramp would not be warranted and any instances of speeding should be reported to the local Garda Station.	Councillor	30/08/2018	0



South Central Area - TAG Meeting Minutes for Noting

(Area Committee Date: 17/10/2018)

Item	Enquiry	SP Ref	Topic	Road	Post	Request Description	Tag Result	Tag Comments	Request By	Received	Sec
8	7004670		Speed Ramps	BUNTING ROAD (SC)	Dublin 12	more effective or additional ramps.	Not Recommended	After a site inspection the area engineer did not notice any speeding in the area at that time so he carried out a 24hr speed survey for Bunting Road. The results of the speed survey came back with readings of 39.80% speed violation but after studying the 85 percentile reading its only 34km/h during the 24hr period. With this information and the fact it's already a 30km zone it would not be recommended to have more ramps installed.	Member of the Public	04/09/2018	0
9	7004746		Stop Sign	KELLS ROAD (SC)	Dublin 12	Blindpost for children with cars coming around the corner.	Not Recommended	After a site visit to Leighlin Road/Kells Road it was noted that this junction was very badly sign posted and will require 2 yield signs RUS 026 and 2 yield road markings (RRM 018) (M 115). Stat 1 - To install a Yield sign and Yield line on the southern junction of Kells Road/Leighlin Road. The location of this sign should be on the green area directly across from house number 72 Kells Road. This should be facing traffic travelling in a easterly direction to Leighlin Road Stat 2 - To install a yield sign and yield line on the northern junction road of Kells Road/Leighlin Road. The location of this sign should be on the northern corner footpath outside of house number 1 facing traffic travelling in a easterly direction to Leighlin Road.	Member of the Public	06/09/2018	0
10	7004747		Speed Ramps	KELLS ROAD (SC)	Dublin 12	Additional ramps on road.	Not Recommended	After a site inspection the area engineer would not recommend additional ramps on Kells Road as the straight part of the road only measures approx 300m and has 4 ramps and on street parking which acts as a natural traffic calming technique on it already. The surrounding roads also have ramps. The area engineer believes that another speed ramp would not be warranted and any instances of speeding should be reported to the local Garda Station.	Member of the Public	06/09/2018	0
11	90049055	SP_37926	No Left Turn	HERBERTON PARK (SC)	Dublin 8	no left turn from SCR onto Herberton Park, the right turn from Herberton Rd onto Herberton Park be made 'except cyclists'	Recommended	After reviewing the no left turn sign on the South Circular Road, south side, on the eastern approach to the junction with Herberton Park it is recommended to modify the information plate to read "Except for Access and cyclists " Also after reviewing the no right turn sign on Herberton Road, south side, on the western approach to the junction with Herberton Park it is recommended to modify the information plate to read "Except for Access and cyclists.	Internal	09/05/2017	0