1	Comhairle Cathrach
W	Bhaile Átha Cliath
	Dublin City Council

South Central Area - TAG Meeting Minutes for Noting (Area Committee Date: 17/07/2019)

04/07/2019 22 Items Page 1 of 4

		ouncit			(Area Committee Dat		Page 1 of	
lten	n Enquiry SP Ref	Торіс	Road	Post	Request Description	Tag Result	Tag Comments	Request By Received
1	7004065	Zebra Crossing	CEANNT FORT (SC)	Dublin 8	Two zebra crossings required for elderly residents.	Recommended	SR Not recommended - A Zebra crossing is not recommended. Due to the nature of the road space and adjoining properties, Dublin City Council do not recommend Zebra crossings as they are generally not as effective as other types of crossings where the onus is on the driver to stop for pedestrians waiting to cross as there is a reliance on more peripheral vision compared to regular signalised crossings, and they may provide a false sense of safety to pedestrians relying on motorists to stop.	Member of 31/07/2018 the Public
2	7004563	Parking Restrictions	SAINT CATHERINE'S LANE WEST (SC)	Dublin 8	Cars parked in laneway making it difficult for pedestrians to walk through.	Recommended	SR Recommended. After a site visit from the Area Engineer, it is not recommended to install Double yellow lines in this lane way but rather install a Clearway instead. Stat – install a 24hr Clearway RUS 010 on the western and eastern sides of St Catherine's West. Start of Clearway should be at the junction of Hanbury lane and run the full length of the lane.	Member of 29/08/2018 the Public
3	7004564	Disab Park Bay General	HANBURY LANE (SC)	Dublin 8	Request for 2 Bays near The Primary Care Centre.	Not Recommended	SR not recommended. After a site visit from the Area Engineer they didn't witness any problems with parking that is already provided through pay and display. People carrying a disabled badge can park here for free so it is not recommended to install 2 Disabled Bays near The Primary Care Centre as there is already good parking on this road.	Member of 29/08/2018 the Public
4	7004854	Yellow Box	SOUTH CIRCULAR ROAD (SC)	Dublin 8	St James Terrace		SR not recommended - the area engineer would not recommend installing a yellow box at the junction of St James Terrace/ South Circular Road as it doesn't meet the criteria of having at least 50 houses . This guideline is in place to avoid a proliferation of yellow boxes in the city.	Member of 13/09/2018 the Public
5	7005011	Disab Park Bay Residential	INGRAM ROAD (SC)	Dublin 8	on the road		Rescind Pay and Display and Permit Parking for 6 metres centred on No. 12 Ingram Road at LS No. 2. Disabled Parking Bay recommended Rescind Pay and Display and Permit Parking for 6 metres centred on No. 12 Ingram Road at LS No. 2.	the Public
6	7005728	P&D/Permit Parking	SOUTH CIRCULAR ROAD (SC)	Dublin 8	Parking scheme for this location.		SR Recommended. After an inspection from the Area Engineer it would be recommended to install Pay, Display &Permit Parking outside Hybreasal House. Stat 1 – Install Pay, Display & Permit Parking starting from LS36 and stretching in an easterly direction for approx. 32m Stat 2 - Install Pay, Display & Permit Parking starting from a point 26.5m west of LS38 stretching in an easterly direction for approx. 65.5m	Member of 01/11/2018 the Public

1	Comhairle Cathrach
W	Bhaile Átha Cliath
	Dublin City Council

South Central Area - TAG Meeting Minutes for Noting (Area Committee Date: 17/07/2019)

04/07/2019 22 Items Page 2 of 4

		ouncit			(Area Committee Dat	e. 17/07/2019)			Page 2 of 4
Item	Enquiry SP Ref	Торіс	Road	Post	Request Description	Tag Result	Tag Comments	Request By	Received Se
7	7005971	Zebra Crossing	SOUTH CIRCULAR ROAD (SC)	Dublin 8	On the road	Not Recommended	SR Not recommended - A Zebra crossing is not recommended. Due to the nature of the road being an arterial route, Dublin City Council do not recommend Zebra crossings as they are generally not as effective as other types of crossings where the onus is on the driver to stop for pedestrians waiting to cross as there is a reliance on more peripheral vision compared to regular signalised crossings, and they may provide a false sense of safety to pedestrians relying on motorists to stop.		14/11/2018 C
8	7006360	Double Yellow Lines (Extend)	NEW IRELAND ROAD (SC)	Dublin 8	At the corner of New Ireland Road and Pormahon Drive is extended down New Ireland Road.	Not Recommended	SR not recommended. After a site visit from the Area Engineer they didn't witness any problems with cars blocking the road for emergency vehicles. The Road is approx. 6m wide which is more than enough room to accommodate parking on one side of the road while allowing for traffic to safely pass through. On street parking also acts as a traffic calming measure so the area engineer would be reluctant to make changes.	the Public	04/12/2018 0
9	7006808	Yellow Box (Extend)	BALLYFERMOT ROAD (SC)	Dublin 10	D Extend the yellow box across the full junction of Ballyfermot Road/Cleggan Park.	Recommended	SR recommended. After a site visit the Area Engineer has noted that there is an issue exiting from Cleggan Road onto the Ballyfermot Road. Stat – Extend the Yellow Box 5m to the west and 5m to the east on both directions on Ballyfermot Road at the junction with Cleggan Road	Member of the Public	11/01/2019 0
10	7006980	Traffic Lights (new)	BROOKFIELD ROAD (SC)	Dublin 8	Traffic lights or yellow box for this location.	Recommended	SR recommended. After a site visit the Area Engineer has noted that there is an issue exiting from Brookfield Road onto the Old Kilmainham Road. Stat – Yellow Box to be Installed at the junction of Brookfield Road/Old Kilmainham Road / Shannon Terrace. This should cover both sides of the junction.	Councillor	21/01/2019 0
11	7007229	Traffic Calming	O'CURRY ROAD (SC)	Dublin 8	Traffic calming measures for this location.	Not Recommended	SR not recommended. After a site inspection the area engineer did not notice any speeding in the area at that time so he carried out a 24hr speed survey on O'Curry Road. This is an extremely lightly trafficked road and that the 85th percentile is only showing at 31km/h during the 24hr period. With this information it would not be recommended to have and traffic calming measures installed.	Member of the Public	04/02/2019 0
12	7007272	Double Yellow Lines	SUSAN TERRACE (SC)	Dublin 8	DYLs for this location.	Not Recommended	SR not recommended - It is not DCC policy to introduce parking restrictions where restrictions are already covered under the law Under The Road Traffic (Traffic & Parking) Regulations, Section 36 paragraph (2) (g) in any place, position or manner that will result in the vehicle obstructing an entrance or an exit for vehicles to or from a premises, save with the consent of the occupier of such premises;" Infringements of the Act should be reported to the Gardai or Dublin Street Parking Services Ph.6022500 for enforcement under the law.	the Public	06/02/2019 1

1	Comhairle Cathrach
¥	Bhaile Átha Cliath
	Dublin City Council

South Central Area - TAG Meeting Minutes for Noting (Area Committee Date: 17/07/2019)

04/07/2019 22 Items Page 3 of 4

	ouncit			(Area Committee Dai	e. 17/07/2019)			Page 3 01 4
Enquiry SP Ref	Торіс	Road	Post	Request Description	Tag Result	Tag Comments	Request By	Received Se
7008616	Yellow Box	CLANBRASSIL CLOSE (SC)	Dublin 8	Yellow Box to facilitate exiting onto Clanbrassil St Upper.	Not Recommended	SR not recommended - the Area Engineer would not recommend installing a yellow box at the junction of Clanbrassil Close and Clanbrassil Street Upper as it doesn't meet the criteria of having at least 50 houses in the cul de sac. This guideline is in place to avoid a proliferation of yellow boxes in the city.	Councillor	23/04/2019 (
7008755	P&D/Permit Parking (Rescind)		Dublin 8	Rescind parking space, or adjust hours, to improve access for cyclists at roundabout.	Recommended	After a site visit from the Area Engineer it was observed that several cars are parking at this location during the peak hours. It is recommended to rescind the single Pay,Display & permit parking spot at LS 25. It would also be recommended to replace it with Double yellow lines.	Internal	30/04/2019 0
7009187	Pedestrian Crossing	CHAPELIZOD HILL ROAD (SC)	Dublin 20)	Recommended	SR recommended - as part of the 2019 Works Programme it has been recommended that a full wrap around Pedestrian crossing will be installed at the junction of Chapelizod Hill Road/Kyle more Road/Le Fanu Road. This is currently in the design stage.	Internal	17/05/2019 0
7009282	Speed Ramps	SPIDDAL ROAD (SC)	Dublin 10) Additional speed ramps due to speeding cars.	Not Recommended	SR not recommended. After a site inspection the area engineer did not notice any speeding in the area at that time so he carried out a 24hr speed survey for Spiddal Road. The results of the speed survey came back with readings of 5.48% speed violation and after studying the 85th percentile reading its only 45km/h during the 24hr period. With this information it would not be recommended to have additional ramps installed.	Internal	22/05/2019 0
7009397	Double Yellow Lines	RIALTO STREET (SC)	Dublin 8	· ·	Not Recommended	covered under the law, such as placing Double Yellow Lines (DYLs) on a corner, as this would lead to a proliferation of same and additional expense due to maintenance, etc."Under the Road Traffic Act it is illegal to block an entrance, park within 5m of a	the Public	28/05/2019 0
7009590	Bus Stop Marking	EMMET ROAD (SC)	Dublin 8	Bus cage for south side of the carraigeway.	Recommended	SR Recommended - After a site inspection the Area Engineer recommended the installation of a bus cage at bus stop 1945. Stat – starting from a point approx. 27.5m east of LS5 moving in an easterly direction for 19m.	Internal	07/06/2019 0
90046705 SP_3519	8 Disab Park Bay General	BASIN VIEW (SC)	Dublin 8	outside the Educate Together National School	Recommended	SR Recommended. After a site inspection the Area Engineer recommended the rescindment of 6m of double yellow lines that are in place and replace them with a general purpose Disabled Bay Stat – On the east side of Basin View starting from a point at LS13 rescind 6m of Double Yellow Lines in a northerly direction Stat – On the east side of Basin View starting from a point at LS13 Install a general purpose Disabled Parking Bay.	Member of the Public	22/11/2016 0
	Enquiry SP Ref 7008616	7008616Yellow Box7008755P&D/Permit Parking (Rescind)7009187Pedestrian Crossing7009282Speed Ramps7009397Double Yellow Lines7009590Bus Stop Marking90046705 SP_35198 Disab Park Bay	Enquiry SP RefTopicRoad7008616Yellow BoxCLANBRASSIL CLOSE (SC)7008755P&D/Permit Parking (Rescind)HERBERTON ROAD (SC)7009187Pedestrian CrossingCHAPELIZOD HILL ROAD (SC)7009282Speed RampsSPIDDAL ROAD (SC)7009397Double Yellow LinesRIALTO STREET (SC)7009590Bus Stop MarkingEMMET ROAD (SC)90046705 SP_35198 Disab Park BayBASIN VIEW (SC)	Enquiry SP RefTopicRoadPost7008616Yellow BoxCLANBRASSIL CLOSE (SC)Dublin 87008755P&D/Permit Parking (Rescind)HERBERTON ROAD (SC)Dublin 87009187Pedestrian CrossingCHAPELIZOD HILL ROAD (SC)Dublin 107009282Speed RampsSPIDDAL ROAD (SC)Dublin 107009397Double Yellow LinesRIALTO STREET (SC)Dublin 87009590Bus Stop MarkingEMMET ROAD (SC)Dublin 890046705 SP_35198 Disab Park BayBASIN VIEW (SC)Dublin 8	Enquiry SP Ref Topic Road Post Request Description 7008616 Yellow Box CLANBRASSIL CLOSE (SC) Dublin 8 Yellow Box to facilitate exiting onto Clanbrassil St Upper. 7008755 P&D/Permit Parking (Rescind) HERBERTON ROAD (SC) Dublin 8 Rescind parking space, or adjust hours, to improve access for cyclists at roundabout. 7009187 Pedestrian Crossing CHAPELIZOD HILL ROAD (SC) Dublin 20 7009282 Speed Ramps SPIDDAL ROAD (SC) Dublin 10 Additional speed ramps due to speeding cars. 7009397 Double Yellow Lines RIALTO STREET (SC) Dublin 8 DYLs for corner, to clarify where residents can park without being clamped. 7009590 Bus Stop Marking EMMET ROAD (SC) Dublin 8 Bus cage for south side of the carraigeway. 90046705 SP_35198 Disab Park Bay BASIN VIEW (SC) Dublin 8 outside the Educate Together	Enquiry SP Ref Topic Road Post Request Description Tag Result 7008616 Yellow Box CLANBRASSIL CLOSE (SC) Dublin 8 Yellow Box to facilitate exiting onto Clanbrassil St Upper. Not Recommended 7008755 P&D/Permit Parking (Rescind) HERBERTON ROAD (SC) Dublin 8 Rescind parking space, or adjust hours, to improve access for cyclists at roundabout. Recommended 7009187 Pedestrian Crossing CHAPELIZOD HILL ROAD (SC) Dublin 10 Additional speed ramps due to speeding cars. Not Recommended 7009282 Speed Ramps SPIDDAL ROAD (SC) Dublin 8 DYLs for corner, to clarify where Lines Not Recommended 7009397 Double Yellow Lines RIALTO STREET (SC) Dublin 8 DYLs for corner, to clarify where carnageway. Not 7009590 Bus Stop Marking EMMET ROAD (SC) Dublin 8 Bus cage for south side of the carraigeway. Recommended 90046705 SP_35198 Disab Park Bay BASIN VIEW (SC) Dublin 8 outside the Educate Together Recommended	Enquiry SP RefTopicRoadPostRequest DescriptionTag ResultTag Comments7008616Yellow BoxCLANBRASSL CLOSE (SC)Dubin 8Yellow Box to facilitate exiting onto Clanbrassi St Upper as for the commended frameword of the Area Engineer word of profileration of yellow boxes in the city.7008755PAD/Permit Parking (Rescind)HERBERTON ROAD (SC)Dubin 8Rescind parking space, or adjust parking space, or adjust parking space, or adjust parking spot at LS 25.Recommended frameword of parking space, or adjust parking spot at LS 25.7009755Packing (Rescind)CHAPELIZOD HILL (SC)Dubin 8Rescind parking space, or adjust parking spot at LS 25.Recommended frameword for seginary backs browns parking spot at LS 25.7009197CroasingCHAPELIZOD HILL (SC)Dubin 2Recommended S Recommended - the as part of the 2019 Works Programme It has been recommended of respicate It with Dubie yelow times as commended frameword at proving parking spot at LS 25.7009197CroasingCHAPELIZOD HILL (SC)Dubin 10Additional speed ramps due to speeding cars.Net Recommended A Res as part of the 2019 Works Programme It has been recommended A reside at parking around Packstina crossing or a 24hr speed survey for Spidal Read. The results of the speed survey for Spidal Read. The results of the carraigeway.7009	Enquiry SP RefTopicRoadPoistRequest DescriptionTag ResultTag CommentsTag CommentsRequest Day7008616Yellow BoxCLANBRASSIL CLOSE (SC)Dublin 8Yellow Box to facilitate exiling onto Clanbrasal Stupper.Not Recommended Installing explication of the price of Clanbrasal Stuee Upper as it doesn't meet the criteria of having tarking at this Castion during the peak hours. It is recommended to result to the single Pay. Displication of Yellow Day at the several cars are parking gitted to base in the day.Councilier7008755P&D/Permit Parking (Rescind)HERBERTON ROAD (SC)Dublin 8Rescind parking space, or adjust several cars are parking gitted to base in the day.Internal several cars are parking gitted to base in the day.Internal meet the carlier of the day.7009757Pedestrian CrossingCHAPELIZOD HILL CrossingDublin 0Recommended to resolution of the single Pay. Displication of Veloce tars with the day.Internal meet the carlier of the day.7009767Pedestrian CrossingCHAPELIZOD HILL DAL ROAD (SC)Dublin 10Additional speed ramps due to speeding cars.Not Recommended SR recommended - as part of the 2019 Works Programme it has speeding or the area angines will be inalized at the incinction of Chapelicad Hill meadure area anginesInternal meadure area angines meadure area angines7009282Speed RampsSPIDAL ROAD (SC)Dublin 10Additional speed ramps due to speeding cars.SR not recommended Area tark angines meadure area angines meadure area angines and altor particida meadure area angines meadure area angines carrie

X	Comhairle Ca Bhaile Átha C Dublin City C	Cliath	Sou		04/07/2019 22 Items Page 4 of 4				
Iten	n Enquiry SP Ref	Торіс	Road	Post	Request Description	Tag Result	Tag Comments	Request By	Received Sec
20	90048610 SP_3747	75 P&D/Permit Parking	DONORE ROAD (SC)	Dublin 8	Introduction of Scheme.	Recommended	Accepted at ballot, Hours Mon-Fri 07.00-19.00. 68 on register, 39 votes returned, 19 for, 15 against, 5 spoiled. The pro-rata vote was 17.5 for and 14.5 against.	Member of the Public	07/04/2017 0
21	90050518 SP_3941	6 P&D/Permit Park (Extend Area)	EMMET ROAD (SC)	Dublin 8	outside No.s 28 & 32.	Recommended	SR Recommended. After a site inspection the Area Engineer noted that the Pay,Display& Permit parking could be extended since the road was relayed as the bus cage has reduced. Stat – On the south side of Emmet road install Pay,Display &Permit parking starting from a point approx 12m east of LS3 moving in a westerly direction for approx 24.5m Stat - On the south side of Emmet road install Pay,Display &Permit parking starting from a point approx. 18.5m west of LS3 moving in a westerly direction for approx. 12.5m.	Member of the Public	27/07/2017 0
22	90050889 SP_3978	9 Continuous White Line	PIM STREET (SC)	Dublin 8	DYLs on junction across from continuous white line on one side only. Suggest DYLs on both sides or rescind exisiting		 d SR Recommended. After a site inspection the Area Engineer recommended the rescindment of some of the solid white lines attached to a Stop Line. Stat 1 – Rescind 9.5m off the continual white line of the Stop line at the junction of Bond St/Pim St. This will leave a total of 5m of continual white line. Stat 2– The Continual White Line of the Stop line at the junction of Long's Place/Pim St should be 10.5m. rescind the remaining line. Stat 3– Rescind 6.5m of the solid white line on Pim Street on the southern side of the junction with Pim Street/Long's Place and Bond st. This should be rescinded back to the yellow lines on the west side of the road. 	Member of the Public	21/08/2017 0