

South Central Area - TAG Meeting Minutes for Noting

07/11/2019

11 Items

(Area Committee Date: 20/11/2019)

Page 1 of 3 Item Enquiry SP Ref Topic Road Post **Request Description** Tag Result **Tag Comments** Request By Received Sec WARRENMOUNT Dublin 8 Extension of Pay & display Hours Recommended Accepted at Ballot to extend hours to Mon-Sun 07.00-24.00. 28 7001900 P&D/Permit Park Member of 06/03/2018 1 (Change Hours) PLACE (SC) on register, 12 votes returned, 8 for, 1 against. 3 spoilt... the Public 7005728 P&D/Permit SOUTH CIRCULAR Dublin 8 Parking scheme for this location. Awaiting Recommended subject to ballot of residents. Member of 01/11/2018 0 ROAD (SC) the Public Parking Survey 7005773 One-Way System BIGGER ROAD (SC) Dublin 12 To prevent motorists using wrong Not SR NOT RECOMMENDED - After a site visit it was noted a One -Member of 05/11/2018 0 side of road, when turning from Recommended Way System would not be appropriate here and that better the Public O'Brien Rd. signage would be more suited. To improve these two junctions the introduction of Yield signs would prove beneficial. 7009550 Double Yellow CONNOLLY Dublin 8 DYLs requested to ensure Not SR Not Recommended - After a site visit the Area Engineer would Member of 05/06/2019 0 Lines GARDENS (SC) access for emergency vehicles. Recommended not be in favour of introducing Double Yellow Lines in Connolly the Public Gardens as it would mean a restriction of parking for people who don't have off street parking at their homes when during a site visit there were no problems witnessed. It would also be refused on the below arounds • It is illegal for a vehicle to park within 5 metres of a junction corner, regardless of whether there are double yellow lines installed or not. • It is illegal to block an entrance/exit to a property without the permission of the property owner. It is illegal to prevent vehicular access along a public roadway. TYRCONNELL ROAD Dublin 8 DYLs or bollards to prevent It is not recommended to install parking restrictions, such as Member of 21/06/2019 0 7009866 Parking Not parking in front of shutter gate to Recommended placing double vellow lines or bollards across driveways, where Restrictions (SC) the Public restrictions are already covered under the law. Under The Road Traffic (Traffic & Parking) Regulations, Section 36 paragraph (2) q: "A vehicle shall not be parked in any place, position or manner that will result in the vehicle obstructing an entrance or an exit for vehicles to or from a premises, save with the consent of the occupier of such premises: "Infringements should be reported to Dublin Street Parking Services tel no. 01 6022500 or the Gardaí as they occur. Double Yellow 7010021 SOUTH CIRCULAR Dublin 8 Extend DYLs southward from Recommended SR Recommended – After a site visit the Area Engineer would be Internal 02/07/2019 0 Lines (Extend) ROAD (SC) iunction, as drivers exiting cannot in favour of extending the existing double yellow lines at the see traffic coming northbound on junction of South Circular Road and the entrance to the National the SCR due to vehicles parked War Memorial Gardens as a measure or increase visibility too close to the junction. Stat – install Double Yellow Lines on the west side of the carriageway of the South Circular Road starting from a point approx. 8.5m North of LS 7 to join up with existing double yellow lines that run around the corner to the side entrance of

Islandbridge Court.



South Central Area - TAG Meeting Minutes for Noting

07/11/2019 11 Items Page 2 of 3

(Area Committee Date: 20/11/2019)

Ite	m Enquiry SP Ref	Topic	Road	Post	Request Description	Tag Result	Tag Comments	Request By	Received Sec
7	7010685	Traffic Calming	BULFIN GARDENS (SC)	Dublin 8	Cars speeding into estate	Not Recommended	A 24hr speed survey was carried out on the 4th of October. The speed survey found that Bulfin Gardens is an extremely lightly trafficked road and that the 85th percentile is only showing at 24km/h which is below the new 30Km/h speed limit. During the survey it was noted that there was only 0.30% of the traffic that broke the speed limit.	Councillor	06/08/2019 0
							Also during a site visit it was noticed that Kickham Road has a School ahead sign (which is actually in the wrong place and will have to be moved) at the entrance. I think the residents have mistaken this as an additional children at play sign.		
							Both Kickham Road and Bulfin Road have the new 30km/h signs which serve as a 3-in-1 sign. Incorporated into these new signs there is a "children at play" and "Slow Zone" sign along with the speed limit. This is to warn motorists that it's a residential area and to expect children.		
_							At present, the Engineer doesn't feel like any additional traffic calming measures need to be done.		
8	7010916 Q 44 SCAC 07/19	Yellow Box	GLENAULIN (SC)	Dublin 2	0	Not Recommended	SR not recommended After a site inspection the area engineer would not recommend a yellow box at the entrance to the Glenaulin estate. The engineer didn't encounter any issues when trying to exit Glenaulin to warrant a yellow box at this junction.		21/08/2019 1
9	7011852	Yield Sign	BIGGER ROAD (SC)	Dublin 1	2 on the road.	Recommended	To improve two junctions on Bigger Road Yield signs are recommended as follows: Stat 1- To install a Yield sign and Yield line outside of 24 Bigger Road. This should be facing traffic travelling in a westerly direction to Bigger Road Stat 2 - To install a yield sign and yield line outside of 18 Bigger Road. The location of this sign should be on the north corner of the smaller triangular green area facing traffic travelling in a westerly direction to Bigger Road from O'Brien Road. Directly across from house number 18.	Internal	16/10/2019 0
10	7011885	Traffic Calming	SPIDDAL ROAD (SC)	Dublin 1	0 "Slow" road markings.	Recommended	Traffic calming recommended in the form of Slow Road markings - After a site inspection it would be recommended to install "SLOW" road markings on the north side of Spiddal Road facing traffic travelling in an easterly direction. This should be located opposite LS 21. Another "SLOW" road marking should be located on the southerr side of Spiddal Road outside house number 62 facing traffic travelling in a westerly direction.		17/10/2019 0



South Central Area - TAG Meeting Minutes for Noting

(Area Committee Date: 20/11/2019)

07/11/2019 11 Items Page 3 of 3

Item Enquiry SP Ref	Topic	Road	Post	Request Description	Tag Result	Tag Comments	Request By	Received Sec
11 7011886	Traffic Calming	CLEGGAN AVENUE (SC)	Dublin 1	I0 "Slow" road markings.	Recommended	Traffic Calming in form of Slow Road Markings recommended - After a site inspection it would be recommended to install "SLOW road markings on the north side of the road facing traffic travelling in an easterly direction. This should be located outside house number 66 Cleggan Ave.		17/10/2019 0
						Another "SLOW" road marking should be located on the southern side of Cleggan Road outside house number 16 facing traffic travelling in a westerly direction.		