



North West Area - TAG Meeting Minutes for Noting

(Area Committee Date: 15/03/2022)

03/03/2022

3 Items

Page 1 of 1

Item	Enquiry	SP Ref	Topic	Road	Post	Request Description	Tag Result	Tag Comments	Request By	Received	Sec
1	7019911		Traffic Calming	JAMESTOWN ROAD (NW)	Dublin 11	Lowering of existing Speed Limit and Traffic Calming Ramps	Not Recommended	Jamestown Road currently has 17no. speed ramps placed at the appropriate distances apart for optimum traffic calming. Jamestown Road is a main traffic artery with significant traffic volumes and therefore has a standard speed limit of 50km/h. This road facilitates numerous bus services and is an emergency route. Therefore, the introduction of additional traffic calming measures for Jamestown Road would not be appropriate and are not recommended. The Transport Advisory Group is not in a position to make any traffic management recommendations in relation to Melville Road and Saint Margaret's Road as the locations concerned are not in the charge of Dublin City Council.	Internal	12/04/2021	0
2	7023394		Double Yellow Lines	HILLCREST PARK (NW)	Dublin 11	cars park on both sides of the road and the residents have great difficulty accessing their driveways	Recommended	Following investigation it is recommended to install double yellow lines on Hillcrest Park at the bend (near no 54), to prevent the hazard created by the parked cars and create a safe access for other vehicles and/or bin lorries. STAT: On the West side of the carriageway of Hillcrest Park, from a point in line with the common boundary of no. 54/53, install approx. 45 meters of Double Yellow Lines in a North direction.	Councillor	26/10/2021	0
3	7023920		Yellow Box	SEAMUS ENNIS ROAD (NW)	Dublin 11	Difficulty with cars taking a left turn from the North Road onto Seamus Ennis Road	Not Recommended	Following investigation on 27.01.2022 during peak time, it was observed that the traffic exiting from North Road onto Seamus Ennis Road wasn't significant and no blocking was noted. Not all locations are suitable for treatment and it is necessary to apply certain criteria before deciding whether a particular site should be marked. Yellow boxes are expensive to maintain and this guideline is in place to avoid a proliferation of yellow boxes in the city. It is not recommended to place a yellow box at this location.	Councillor	30/11/2021	0