



North West Area - TAG Meeting Minutes for Noting

(Area Committee Date: 19/07/2022)

Item	Enquiry	SP Ref	Topic	Road	Post	Request Description	Tag Result	Tag Comments	Request By	Received	Sec
1	7017355		Loading Bay	FITZMAURICE ROAD (NW)	Dublin 11	on the road	Recommended	Recommended – a loading bay is recommended for Fitzmaurice Road. STAT: Install a loading bay (RRM 009) on the north side of Fitzmaurice Road, from the edge of the indented parking bay south of 7 Fitzmaurice Road, for 15m, in an easterly direction, with associated signage and timeplate (P 051) "7:00 – 19:00 Mon-Sat"	Councillor	13/10/2020	1
2	7024415		TAG General Engineer Query	JAMESTOWN ROAD (NW)	Dublin 11	A new left lane or a review of the junction to examine the traffic flow	Not Recommended	Not recommended – following an on-site visit, no issue with regards to traffic flow was observed on Jamestown Road, turning left onto Sycamore Road. The area engineer did not observe any significant build-up of vehicles wishing to turn left onto Sycamore Road. Introducing a left turn lane at this junction would be contrary to Dublin City Council's commitment to sustainable mobility.	TD	17/01/2022	0
3	7026841		TAG General Engineer Query	BALLYMUN ROAD (NW)	Dublin 9	At this junction could the right lane be marked for people going right (back onto the Ballymun Road) and the left lane be for people going straight (Mobhi Road) & left (Griffith Ave).	Not Recommended	Following a recent site visit, it was observed that the "Lane Indication Arrows" on Ballymun Road were found to be adequate to inform the orderly flow of traffic through the junction and indicate the correct lane to take. Traffic must proceed in the direction of the arrow provided. As such, no change in road markings is recommended at this time.	Member of the Public	24/05/2022	0