

North Central Area - TAG Meeting Minutes for Noting

08/03/2022 7 Items Page 1 of 2

(Area Committee Date: 21/03/2022)

Iter	m Enquiry SP Ref	Topic	Road	Post	Request Description	Tag Result	Tag Comments	Request By	Received Sec
1	7017025	School Warden	EDENMORE CRESCENT (NC)	Dublin 5	school warden requested outside the church to assit children entering the back entrance of the school due to new covid arrangements.	Recommended	The Road Safety unit carried out a traffic count on Edenmore Crescent. The number of children crossing the road during the two days of count did not meet the criteria for an additional school warden.	the Public	22/09/2020 0
2	7017110	School Warden	THE HOLE IN THE WALL ROAD (NC)	Dublin 13	on Hole in the wall road, close to new Vesta apartments and Trinity Donaghmede football club (that is inside the Father collins park) exiting onto little walkpath between Parkside row and Parkside Gardens	Recommended	Following Road Safety inspection a school warden is not I recommended at this location due the width of the road, the traffic island and the general behaviour of motorists,cyclists and pedestrians.		28/09/2020 0
3	7017273	School Warden	MOUNT PROSPECT AVENUE (NC)	Dublin 3	across mount prospect avenue a the junction with Seafield Avenue		Following Road Safety inspection a school warden is recommended on Mount Prospect Avenue.	Member of the Public	08/10/2020 0
4	7020777	School Warden Crossing Box	GREENCASTLE ROAD (NC)	Dublin 17	7 This junction is dangerous for the school warden to cross.	e Recommended	Following inspection, on Greencastle Road it is recommended to install a School Warden Crossing Patrol Point Marking (M121) at the school warden stands. Stats: On Greencastle Road, on the North side of the carriageway, from a point commencing approx. 5 meters West from West kerb line of Greencastle Park, install 2.4 meters in a West direction SCHOOL WARDEN CROSSING PATROL POINT (M 121) to extend across both lanes.	the Public	26/05/2021 0
5	7021885	Yield Sign (Rescind)	GRACE PARK HEIGHTS (NC)	Dublin 9	Take away the yield sign , put stop sign (if possible) on left hand side when you turn corner put half way down the road double yellow lines	Not Recommended	The existing Yield sign is appropriate in indicating priority at the junction concerned. Under the Road Traffic Regulations, traffic on a road ending at a T junction must give way to traffic from either direction on the other road. Stop / Yield signs are not necessary where normal rules of the road apply, moreover such signs/markings are only provided on approaches to major junctions, otherwise this would lead to a proliferation of signs throughout residential estates. Implementation of parking restrictions in form of double yellow lines on Grace Park Heights could create parking difficulties for the residents and may also result in an increase in speed in this residential area in accordance with DMURS guidelines. Alterations to the current parking arrangements are not recommended at this time for the reasons given here.		29/07/2021 0
6	7023864	Yellow Box	HOWTH ROAD (NC)	Dublin 3	Install yellow box in line with school warden's spots on the footpath to assist with children crossing.	Recommended	Following inspection, on Howth Road at Mixed National School, it is recommended to install a School Warden Crossing Patrol Point Marking (M121) at the school warden stands. Stats: On Howth Road, on the South side of the carriageway, from a point commencing 2 meters West from West pylon gate of Clontarf & Scots Church, install 2.4 meters in an West direction SCHOOL WARDEN CROSSING PATROL POINT (M 121) – to avoid the school entrance / dished kerb.		25/11/2021 0



North Central Area - TAG Meeting Minutes for Noting

(Area Committee Date: 21/03/2022)

08/03/2022 7 Items Page 2 of 2

7 7024565 Yellow Box COLLINS AVENUE Dublin 5 a yellow box is needed so people will take more notice. Recommended are already covered under the law. Under The Road Traffic the Public (Traffic & Parking) Regulations, Section 36 paragraph (2); A vehicle shall not be parked: (i) on a foot way, a grass margin or a median strip. Illegal parking should be reported to the Gardai or					`		,	· ·
EAST (NC) people will take more notice. Recommended are already covered under the law. Under The Road Traffic the Public (Traffic & Parking) Regulations, Section 36 paragraph (2); A vehicle shall not be parked: (i) on a foot way, a grass margin or a median strip. Illegal parking should be reported to the Gardai or	Item Enquiry SP Ref	Topic	Road	Post	Request Description	Tag Result	Tag Comments	Request By Received Se
Dublin Street Parking Services (tel no. 01 6022500), for enforcement under the law.	7 7024565	Yellow Box		Dublin 5	•		ed are already covered under the law. Under The Road Traffic (Traffic & Parking) Regulations, Section 36 paragraph (2); A vehicle shall not be parked: (i) on a foot way, a grass margin or a median strip. Illegal parking should be reported to the Gardai or Dublin Street Parking Services (tel no. 01 6022500), for	