

South Central Area - TAG Meeting Minutes for Noting

(Area Committee Date: 11/12/2019)

Item	Enquiry	SP Ref	Topic	Road	Post	Request Description	Tag Result	Tag Comments	Request By	Received	Sec
1	7005774		TAG General Engineer Query	O'BRIEN ROAD (SC)	Dublin 12	Review & improve road safety measures at this junction.	Recommended	After a site visit it was noted a One - Way System would not be appropriate here and that better signage would be more suited to improve these two junctions the introduction of Yield signs would prove beneficial. Therefore the following are recommended: Stat 1- To install a Yield sign and Yield line outside of 24 Bigger Road. This should be facing traffic travelling in a westerly direction to Bigger Road Stat 2 - To install a yield sign and yield line outside of 18 Bigger Road. The location of this sign should be on the north corner of the smaller triangular green area facing traffic travelling in a westerly direction to Bigger Road from O'Brien Road. Directly across from house number 18.	Senator	05/11/2018	0
2	7008122		Cycle Track	CHAPELIZOD ROAD (SC)	Dublin 8	Bus Stop recommendations	Recommended	SR Recommended – After a site visit it was noticed that several bus stops come into direct conflict with the segregated cycle lane. Stat 1 for bus stop outbound 2194 – install new sign RUS058 on approach to bus stop waiting area. Stat 2 - install new yield road markings and yield line on the cycle lane on approach to bus stop waiting area. Stat 3 – Remove centre line of the cycle lane for the length of the bus cage Stat 1 for bus stop outbound 2193 – install new sign RUS058 on approach to bus stop waiting area. Stat 2 - install new yield road markings and yield line on the cycle lane on approach to bus stop waiting area. Stat 3 – Remove centre line of the cycle lane for the length of the bus cage Stat 1 for bus stop inbound 2247 – install new yield road markings and yield line on the cycle lane on approach to bus stop waiting area. Stat 1 for bus stop inbound 2248 – install new sign RUS058 on approach to bus stop waiting area. Stat 2 - install new yield road markings and yield line on the cycle lane on approach to bus stop waiting area. Stat 3 – Remove centre line of the cycle lane for the length of the bus cage Stat 1 for bus stop inbound 2249 – install new sign RUS058 on approach to bus stop waiting area. Stat 2 - install new yield road markings and yield line on the cycle lane on approach to bus stop waiting area. Stat 3 – install bus cage starting 1m east of the bus stop pole 2249 stretching westward for 13m Stat 4 –Remove centre line of the cycle lane for the length of the bus cage	Internal	27/03/2019	0
3	7011991		Yield Sign	SPIDDAL ROAD (SC)	Dublin 10	Yield sign for this junction.	Recommended	SR Recommended – After a site visit it was noticed that dangerous driving is occurring on Spiddal Road. It was recommended to introduce a Yield sign RUS026 accompanied by a Yield Line RRM 018 on Spiddal Road at the junction with Blackditch Road.	Internal	23/10/2019	0

South Central Area - TAG Meeting Minutes for Noting

(Area Committee Date: 11/12/2019)

28/11/2019

15 Items

Page 2 of 3

Item	Enquiry	SP Ref	Topic	Road	Post	Request Description	Tag Result	Tag Comments	Request By	Received	Sec
4	7011992		Yield Sign	SPIDDAL ROAD (SC)	Dublin 10	Yield sign for this junction.	Recommended	SR Recommended – After a site visit it was noticed that dangerous driving is occurring on Spiddal Road. It is recommended to introduce a Yield sign RUS026 accompanied by a Yield Line RRM 018 on Claddagh Road at the junction with Spiddal Road.	Internal	23/10/2019	0
5	7011993		Yield Sign	SPIDDAL ROAD (SC)	Dublin 10	Yield sign for this junction.	Recommended	SR Recommended – After a site visit it was noticed that dangerous driving is occurring on Spiddal Road. It is recommended to introduce a Yield sign RUS026 accompanied by a Yield Line RRM 018 1) on Moycullen Road at the junction with Spiddal Road and 2) on Moycullen Road at the junction with Claddagh Road.	Internal	23/10/2019	0
6	7011994		Yield Sign	SPIDDAL ROAD (SC)	Dublin 10	Yield sign for this junction.	Recommended	Recommended – After a site visit it was noticed that dangerous driving is occurring on Spiddal Road. Recommended to introduce Yield signs RUS026 accompanied by Yield Lines RRM 018 be provided 1) on Spiddal Park at the junction with Spiddal Road and 2) on Spiddal Park at the junction with Oranmore Road.	Internal	23/10/2019	0
7	7011995		Yield Sign	SPIDDAL ROAD (SC)	Dublin 10	Yield sign for this junction.	Recommended	SR Recommended – After a site visit it was noticed that dangerous driving is occurring on Spiddal Road. It is recommended to introduce Yield signs and Yield Lines RRM 018 1) on Claddagh Green at its western and eastern junctions with Spiddal Road and 2) on Claddagh Green at its western and eastern junctions with Claddagh Road.	Internal	23/10/2019	0
8	7011996		Yield Sign	SPIDDAL ROAD (SC)	Dublin 10	Yield sign for this junction.	Recommended	SR Recommended – After a site visit it was noticed that dangerous driving is occurring on Spiddal Road. It is recommended to introduce a Yield sign accompanied by a Yield Line RRM 018 on Carna Road at junctions with 1) Spiddal Road and 2) Claddagh Road.	Internal	23/10/2019	0
9	7011997		Yield Sign	SPIDDAL ROAD (SC)	Dublin 10	Yield sign for this junction.	Recommended	SR Recommended – After a site visit it was noticed that dangerous driving is occurring on Spiddal Road. It is recommended to introduce a Yield sign RUS026 accompanied by a Yield Line RRM 018 1) on Inagh Road at the junction with Spiddal Road and 2) Inagh Road at the junction) with Claddagh Road.	Internal	23/10/2019	0
10	7011998		Children Crossing Sign	SPIDDAL ROAD (SC)	Dublin 10	Children crossing sign for this junction.	Recommended	SR Recommended – After a site visit it was noticed that dangerous driving is occurring on Spiddal Rd. It was recommended to introduce a “Children Crossing” sign and “slow” road markings. Recommended to install a “Children Crossing” sign W 142 on the north side of the carriageway at the entrance to Spiddal Road facing traffic coming from Blackditch Road accompanied by a “Slow” road marking located across from 127 Spiddal Road on the north side of the carriageway facing traffic coming from Blackditch Road.	Internal	23/10/2019	0

South Central Area - TAG Meeting Minutes for Noting

(Area Committee Date: 11/12/2019)

28/11/2019

15 Items

Page 3 of 3

Item	Enquiry	SP Ref	Topic	Road	Post	Request Description	Tag Result	Tag Comments	Request By	Received	Sec
11	7011999		Children Crossing Sign	SPIDDAL ROAD (SC)	Dublin 10	Children crossing sign for this junction.	Recommended	SR Recommended – After a site visit it was noticed that dangerous driving is occurring on Spiddal Rd. It was recommended to introduce a “Children Crossing” sign and “slow” road markings. Recommended to install a “Children Crossing” sign W 142 on the south side of the carriageway at the entrance to Spiddal Road facing traffic coming from Clifden Road accompanied by a “Slow” road marking located outside 5 Spiddal Road on the south side of the carriageway facing traffic coming from Clifden Road.	Internal	23/10/2019	0
12	7012000		Children Crossing Sign	CLEGGAN ROAD (SC)	Dublin 10	Children crossing sign for this junction.	Recommended	SR Recommended – After a site visit it was noticed that dangerous driving is occurring on Cleggan Road/ Cleggan Ave. It was recommended to introduce a “Children Crossing” sign and “slow” road markings. Recommended to install a “Children Crossing” sign W 142 accompanied by two “Slow” road markings. The “Children Crossing” sign and the “slow” road markings should be provided on the south eastern side of the carriageway outside 8 Cleggan Road facing traffic coming from Drumfinn Ave. Install another “Slow” road marking outside 64 Cleggan Ave. This should be provided on the north side of the carriageway facing traffic coming from Cleggan/Cloiginn park.	Internal	23/10/2019	0
13	7012385		Double Yellow Lines	SOUTH CIRCULAR ROAD (SC)	Dublin 8	On the west side of the SCR	Recommended	SR Recommended – After a site inspection it was noticed that cars are parking on a stretch of carriageway between New Ireland Road and Mountshannon Road on the South Circular Road Stat - Install Double yellow lines from the junction of New Ireland Road to the junction of Mountshannon Road on the western side of the carriageway. Stat - Install Double yellow lines on the eastern side of the carriageway outside the Brookfield Court apartments on the South Circular Road across from the junction of New Ireland Road. Running for the whole length of the apartment complex.	Councillor	13/11/2019	0
14	7012543		Bus Stop Marking	SOUTH CIRCULAR ROAD (SC)	Dublin 8	Install bus cage marking and any associated DYLS.	Recommended	SR Recommended – After a site visit it was noticed that cars were parking at the bus stop and causing issues for the bus. Stat 1)– Install a Bus Cage at Bus stop 1379 starting from a point 9m south of LS52 on the eastern side of the carriageway running for 16m in a northerly direction. Stat 2) install Double Yellow Lines approx. 7m north of LS52 running in a northerly direction to meet up with existing lines on the eastern side of the carriageway.	Internal	21/11/2019	0
15	90048570	SP_37433	Add Pedestrian Phase	BRIDGE STREET LOWER (SC)	Dublin 8	Full wrap-around	Not Recommended	It has been estimated the the above works would be significantly over the limit for works which can be carried out by TAG. The matter is to be referred to the Sustainable Trannsport team for future consideration and ownership.	Member of the Public	07/04/2017	0