


### **Presentation content:**

- 1. Irelands Bathing Waters
- 2. Dublin City Council Bathing Waters
- 3. Bathing Water Regulations 2008
- 4. 2023 Bathing Season
- 5. 2024 Bathing Season
- 6. Bathing Waters Task Force
- 7. Next Steps






# **Ireland's Bathing Waters – 2022 EPA Report**



Classification	Number of bathing waters in 2021	Number of bathing waters in 2022
Excellent	115	117
Good	19	20
Sufficient	10	7
Poor	2	3
New/Changes	2	1
Total	148	148

- National Bathing Water Quality improving incrementally year on year (EPA 2022 Bathing Report).
- Currently 148 identified bathing waters managed under the Bathing Water Regulations.
- Designated waters annually classified by EPA.
- 4 year statistical assessment as set out in Regulations.
- 144 (97%) met or exceeded the minimum required standard of Sufficient.
- UWW deemed likely cause of bathing water incidents in 2022.
- Next report due April/May 2024.
- Changes to classifications and designations announced.





# **Dublin City Council Bathing Waters**




#### **Dublin City Council Bathing Waters**

Location	Туре	Anticipated 2024 Classification (2020-2023)
Dollymount Strand	Designated bathing area	Good
Sandymount Strand	Designated bathing area	Poor*
Half Moon	Other monitored water*	New*
North Bull Wall	Other monitored water	n/a
Shelly Banks	Other monitored water	n/a
Merrion Strand	Other monitored water	n/a



# **Bathing Water Quality Regulations 2008**



#### **Brief overview:**

- Driven by the BWD Protect bather health
- Designated bathing season is defined as 1<sup>st</sup> June to 15<sup>th</sup> September
- Sample frequency 4 times (min.) per designated bathing location across the season
- Sample parameters
- Methods of analysis
- Information the public
- Incident response and reporting
- Consultation with Health Service Executive
- Annual classification by Environmental Protection Agency









#### **Brief overview:**

- Of 120 scheduled samples taken across the 6 bathing locations, the following percentage of samples returned as either Excellent or Good quality;
- 95% at the Half Moon;
- 90% at Sandymount & Dollymount Strands;
- 80% at Merrion Strand and Shelley Banks;
- 60% at the North Bull Wall







### **Monitoring overview:**


www.beaches.ie

- The monitoring schedule is agreed with the EPA in advance of the season and is published online by Dublin City Council and the EPA.
- DCC monitors bathing water quality all year round, with water quality monitored on a fortnightly basis outside of the season.
- Water quality sampling is predominantly used as an effective retrospective analysis tool.

																	2	023 Ba	thing	Seaso	n															2023-20
	DATE OF SAMPLE	02/05	16/05	22/0	5 06/06	12/00	13/06	15/06	18/06	20/06	21/06	28/06	30/06	03/07	12/07	13/07	17/07	19/07	23/07	24/07 *	27/07	31/07	01/18	08/08	14/08	15/08	20/08	22/08	28/08	29/0	03/09	11/09	12/09	18/09	25/09	10/10 2
Areas	DOLLYMOUNT												-					-	<b>~</b>																	
Designated Bathing Areas	SANDYMOUNT																	-	<b>Z</b>	<b>~</b>																
Areas	MERRION							-		-	-					-		-	<b>~</b>	-	-							-					-	-		
Bathing	SHELLEY BANKS							-		-	-					-		-	~	-	-							-					-	-		
signated	HALF MOON							-		-	-		-			-		-		-	-							-					-	-		
Non-De	NORTH BULL WALL CAUSEWAY							-		-	-					-				-				$\approx$												
																					\								Y	1	4					
	Dotailed table available t	م طر	wh	000	l fro	m +1	20 D	\ <b>\</b> /D	O w/	ohc	ito o	nd																								
	Detailed table available to download from the PWBO website and										OLIK	Voil																								

#### **Brief overview:**


- July 2023 wettest on record. Ireland had 217 % of its 1981-2010 Long term Average (LTA) rainfall in July 2023.
- July 2023 had more than 4 times the amount of rain observed in July 2022 and more than twice that observed in July 2021.
- Poor weather prompted 4 bathing restrictions at Sandymount in July in order to protect bather health.
- EPA observed significant increase in warnings raised nationally during 2023 bathing season.
- All warnings raised and removed in consultation with HSE
- EPA **notified** of relevant incidents <u>www.beaches.ie</u>





### **Changes to expect in 2024:**


**Sandymount Strand**Anticipated 2024 classification



Sandymount Strand BW Analysis Results									
Year	Excellent	Good	Sufficient	Poor					
2019	17	2	0	1					
2020	19	0	0	1					
2021	14	0	1	5					
2022	15	3	0	2					
2023	12	6	2	0					

2023	2022	2021	2020
None	Sufficient Quality	Sufficient Quality	Sufficient Quality

Half Moon Bathing location Anticipated 2024 designation





### **Bathing Water Task Force**



BWTF was established in 2019.

#### **Agencies:**

- Dublin City Council
- Dun Laoghaire Rathdown County Council
- Uisce Éireann
- Dept. Housing, Local Government & Heritage (WAU)
- Fingal County Council (2022)

#### **Relevant Legislative remit:**

- Bathing Water Regulations 2008;
- Water Pollution Act 1977, as amended;
- EU Water Framework Directive 2000, and;
- EU Recast Urban Wastewater Directive (Draft)

#### Goal:

Return Merrion Strand to a Sufficient BW Status, as per all designated bathing areas.

#### Oversight:

HSE (Public Health) EPA (Regulator) Dept (Policy)













# **Bathing Water Task Force - Activities**

### **Key areas of activity:**

7.1	Baseline understanding	KPI to measure impacts over time	Water quality trends					
7.2	Understanding of Impacts	UV light at RWWTP outfall	Dublin Bay tidal flows					
	from Wastewater discharges							
7.3	Scientific Support	Advisory services from Central Labo	ratory					
7.4	Engage in scientific assessments	Collaborate with Third level Institute	es					
7.5	Public Engagement	Review ongoing public engagement records and procedures.						
		Address common issues, E.g. Ectoca	rpus & Real time BW quality information					
7.6	Communications	Consistent messaging and channels across BWTF agencies – Awareness campaign						
7.7	Elm Park Stream	Specific study and onsite investigations						
7.8	Beach activity	Review sampling practices and data	collection requirements					
7.9	Wildlife	Assess impacts from wildlife/biosphere on bathing waters - Ectocarpus						
7.10	Support Innovation	Support and/or validate third party innovations – Smart Signage						
7.11	Reporting	Ensure regular progress reporting and inform NBWEG						
7.12	Consideration of applicable legislation	Consider legislative requirements, and effectiveness (EU BW Directive).						
7.13	Acclimatize Project	Using research to preserve and enhance the marine and coastal environment in Du						
		Bay	www.ars					

Dublin City Council
Comhairle Cathrach Bhaile Átha Cliath

# **Bathing Water Task Force - Activities**

#### **Collaborations:**

### 7.13 the Acclimatize Project and proposed continuation


**Objective**: examining the concerns and circumstances relating to faecal contamination of rivers and bathing waters as well as assessing the impact of climate change driven effects on water.

...specifically Merrion Strand, Sandymount Strand and Dollymount Strand

Microbial Source Tracing (MST) analysis: identify known markers to identify prominent source of bacteria in water samples; Human, dog, gull or ruminant











### **Next Steps**

- Activities identified; BWTF Report <a href="https://www.dublincity.ie/sites/default/files/2023-10/BWTF%20Report%202023%20-%20FINAL\_0.pdf">https://www.dublincity.ie/sites/default/files/2023-10/BWTF%20Report%202023%20-%20FINAL\_0.pdf</a> .
- Integrated Catchment Management planning in line with Recast Urban Waste Water Directive (DRAFT)
- SUDS Nature Based Solutions
- Communications; Consistent and concise messaging to the public
- The water quality monitoring programmes will continue on an all year around basis and are available to view on the council's website and the EPA's beaches.ie.
- Collaboration with the UCD Acclimatize project concluded in June 2023 and the BWTF is keen to continue to support their essential
  insights into near shore pollution sources which inform LA activities
- **Pollution investigations** misconnections, unauthorized discharge, trade effluent.
- **Agency collaboration**; As the BWTF continues to meet on a monthly basis, with an aim to deliver a homogeneous public service along County Dublin's coastline to those who wish to enjoy it












### **PWBO Website**



### Address - https://www.dublincity.ie/residential/environment/protection-water-bodies

### **Available reports:**

- 2019 2023 BWTF Report
- 2023 Bathing Season
- Bathing Water sampling schedule
- Sandymount Strand Management Plan for Improving Water Quality
- Latest Bathing Water sampling results
- BW Location maps
- Statutory Notifications
- FAQ's and more

















PWBO Water Framework Directive section @ wfd@dublincity.ie

PWBO Water Pollution Control section @ waterpollution@dublincity.ie

